

Signature Tester

Ram-Lock Failure Pyramid

Ram stuck closed during well control event

Ram won't unlock subsea, pull stack for repairs

Ram won't unlock at surface. Some lost time as repairs are carried out. If you are lucky this happens at surface

Ram unlocks but operation is erratic (This can be found with our signature test)

Subsea failures are similar to accidents. There are unsafe acts and unsafe conditions that precede the incident. Our equipment is designed to help uncover these conditions.

Ideas, Innovation and Implementation



© 2012, The Subsea Company